



# Resistance Soldering, The Basics



A Clinic Presented at the 2015  
NMRA National Convention , Portland, OR  
September, 2015  
By Gary Butts #146478

## Normal Soldering Tools



Soldering Pencil

Good small heat area, low heat capacity.



Soldering Iron

High heat capacity, large tip area is cumbersome for small parts.



Butane-Air and Acetylene-Air Torches

Very high heat capacity, relatively large heat area



Oxygen-Acetylene Torch

Very high heat capacity, smaller heat area



## Resistance Soldering Rigs

### Inexpensive Tweezers System

- Two heat ranges, 63W at High Power
- Manual heat range change
- Probe only
- With foot switch
- Approximate cost \$175



### Medium Range Tweezers System

- Continuous heat range, 0-250 Watts
- Probe only
- With foot switch
- Approximate cost \$400



### Medium Range Probe System

- Continuous heat range, 0-250 Watts
- Tweezers only
- With foot switch
- Approximate cost \$485



### High End Combination System

- Five heat range, 0-300 Watts
- Tweezers and Probe
- With foot switch
- Starter set of flux and solder assortment
- Approximate cost \$680



# Resistance Soldering Rigs

## How do they work?

High current creates localized heat on the probes and in the parts

$$\text{Heat} = \text{Power} = (\text{Current})^2 / \text{Resistance (Joint and Probe)}$$

Low Voltage = Safe to touch

Setting	Voltage	Current	Power
1	1.1 (2.5)V	59A	65W*
2	1.3 (2.7)	62	81
3	1.5 (3.1)	74	111
4	1.65 (3.5)	88	145
5	1.85 (4.0)	103	191



( ) : Open circuit voltage

\*Compare to normal 60W soldering pencil

High heat concentrated in a very small area gives a rapid local temperature rise.

This allows us to quickly form joints without having to heat large areas of our models which can endanger other close by solder joints.

When the current (foot switch) is off or the probe or tweezers are not pinched, there is no current flow and therefore no heat is generated. There may be residual heat in the probe tips from the previous joint formation which cools relatively rapidly.



# Solder

In the absence of contamination, solder forms an alloy with the parent metal at temperatures well below the melting point of the parent.

## Common solder alloys

40/60	460 degrees F (230 degrees C)
50/50	418 degrees F (214 degrees C)
60/40	374 degrees F (190 degrees C)
63/37	364 degrees F (183 degrees C)
95/5	434 degrees F (224 degrees C)

-60/40 most common and general use solder

-95/5 Tin-Antimony alloy, lead free

Melting temperature of most Brass alloys 1800 degrees F

Melting temperature of most Copper alloys: 2000 degrees F

Melting temperature of Nickel-Silver: 2000

# Solder

## Forms of solder

- Wire, Bar: Solid solder alloy
- Flux core: A hollow tube of solder with flux dispersed inside
- Paste: A mixture of fine solder particles with stiff flux.



# Flux

## Why use flux?

### Corrosive (acid) flux

-Used to clean the oxidation from the parent metals to facilitate the alloying process. As the surface of the metals are heated the flux boils increasing the effectiveness of the acid to clean residue and oxidation from the parent and solder metal.

-Best for Brass, Monel, Steel

-Must be cleaned to prevent continued corrosion (etching) of the joint metals

Soap and water + brush

Dishwasher?

Ultra-sonic cleaner

### Non-Corrosive (rosin) flux

-Used to promote solder flow and reduce oxidation.

-Best for Copper

-Does not have to be cleaned but leaves a residue

Clean the residue with Acetone

## Flux



Corrosive (Acid) and Rosin fluxes are available  
In either paste or liquid forms

## Pre Clean

Direct contact with the parent metal is required to form the solder alloy

Remove all paint, grease, etc

Most Brass models have a protective lacquer coating that must be removed to form a good joint and will burn black when heated.

Acetone works well for paint and grease removal

Micro-brush, Q-tip or Pipe cleaner

## Tinning

Used to pre form the initial molecular alloy on the parent metal(s).

Facilitates rapid joint formation

Insures a "quality" bond



## Solder Wick

Use to remove excess solder or completely remove through hole components



## Steps to Resistance soldering

1. Clean the surfaces to bare metal.

Remove flaking paint and corrosion by scraping, sanding, filing etc.

Remove paint residue with Acetone.

2. Add flux

Either liquid or solder/flux paste mix.

3. Tin

Where possible tin both surfaces with solder prior to forming the joint.

4. Position the parts.

Fixture or mechanically hold the parts if possible. Holding the parts by hand is convenient but can lead to burned finger tips! The parts do get hot.

5. Apply heat

Use either type of probe to just melt and flow the solder. Apply solder simultaneously if not using solder paste. Do not linger, the joint is formed the instant the solder melts and flows together. Remove the heat by releasing the current with a foot pedal but leave the probe or tweezers in place until the joint chills solid.

6. Remove excess solder

Solder Wick

Xacto blade

7. Remove the flux residue

Clean corrosive flux with soap and water.

Clean rosin flux with Acetone.



## Probe Resistance Soldering tool

Requires a ground lead to complete the current flow

Metal vice

Use similar to a torch

Best for

Rear heating

Large components

Flowing joints

Stitching

Always heat the larger (thicker) part with the probe

Best on:

"T" Butt Joint, Front and Back heat eyebrows, running boards

Through hole grab irons, clean-outs, NBW castings

Flat grab irons, steps, etc. on large surfaces



## Tweezers Resistance Soldering tool

No ground lead required

Use similar to Tweezers

Best for

Small components: grab irons, glad hands, steps

Clamping action between components

Edge joints on small flanges

Grab irons close to an edge

Eyelets

